

Notice



- ☐ CORRECTION ☒ PRODUCTION CHANGE
☐ SERVICE FLASH ☐ ADD INFORMATION

FILE NO.

REVISION 0

Please add this notice to the Service Manual listed below.

Category: **COLOR TELEVISION**

Date: **OCTOBER / 22 / 2012**

Model: **DP39842**

Effective from : Chassis No. **P39842-04**

Destination: **U.S.A. / CANADA**

REF : **No. SM780201-04**

NOTE: Match the Chassis No. on the unit's back cover with the Chassis No. in the Service Manual. **If the Service Manual Chassis No. does not match the unit's**, additional Service Literature is required. This chassis is similar to Chassis No. P39842-00. Only the **difference** Service Information is given in this manual. For detailed Service Information, refer to the **Original** Service Manual and **Notices** for Chassis No. P39842-00 used in Model DP39842-Z6SE (SM780201).

SERVICING SHOULD BE PERFORMED BY ONLY TRAINED AND QUALIFIED SERVICE PERSONNEL.

1. IN THE SERVICE ADJUSTMENTS

PAGE 4 ON-SCREEN SERVICE MENU

Item No. **088 OP2 Data** should be changed from **21h** to **22h** in the table and in Note 2.

2. IN THE CHASSIS ELECTRICAL PARTS LIST MISCELLANEOUS

The reason for change.

- A : Misprint B : Quality Reliability C : Standardization
D : Design E : Add as a possible sub F : Schematic location change
G : Purchasing Request

Page & Section	Schematic Location		Part No.	Description	Q'ty	Interchangeability	Reason
Page 19, Chassis Electrical Parts List	▲A100	Old	1LG0B10Y10100	ASSY,PWB,ANALOG-COMP-Z6SE	1	NO	D
		New	1LG0B10Y101A0	ASSY,PWB,ANALOG-COMP-Z6SJM	1	NO	
	▲A200	Old	1LG0B10Y10200	ASSY,PWB,DIGITAL_Z6SE	1	NO	D
		New	1LG0B10Y102A0	ASSY,PWB,DIGITAL_Z6SJM	1	NO	
	▲EL901	Old	1AV4T40C32800	LCD(V390HJ1-L01)	1	NO	D
		New	1AV4T40C33900	LCD(T390HVN01.0)	1	NO	
		Old	1AV4T40C32801	LCD(V390HJ1-L02)	1	NO	D
		New	1AV4T40C33900	LCD(T390HVN01.0)	1	NO	
		Old	1AV4T40C32802	LCD(V390HJ1-L02)	1	NO	D
		New	1AV4T40C33900	LCD(T390HVN01.0)	1	NO	
	▲U901	Old	N0AB3EJ00002	UNIT,POWER-Z6SE	1	NO	D
		New	N0AB3EJ00004	UNIT,POWER-Z6SJ	1	NO	
	▲WK5LV -PN	Old	1LB4W30B26300	CORD, 51P-40P(LVDS)	1	NO	D
		New	1LB4W30B26300	CORD, 51P-40P(LVDS)	1	NO	

For parts or service contact:

Sanyo Manufacturing Corporation
P.O. Box 2000
3333 Sanyo Road
Forrest City, Arkansas 72335-2000